

IN THE DRAWINGS

Figure 3a is amended herein to correct errors in the previously submitted drawing sheet. All amendments to Figure 3 are supported in and make the drawing consistent with the specification. A clean replacement sheet for Fig. 3a is also provided.

REMARKS

All amendments to Figure 3a herein are for the purpose of correcting errors in the previously submitted drawing. All amendments to Figure 3 are supported in and bring the drawing into agreement with the specification.

Specifically, the labels 420 and 430 have been correctively amended to read 320 and 330 respectively. This correction brings Figure 3a into agreement with the specification as amended in applicants' January 1, 2003 response to the October 8, 2002 office action (Applicants' response dated January 1, 2003, page 2, paragraph 1). Thus, by this corrective amendment, the references in the specification to the die 330 and the underfill 320 in Figure 3a now agree with the numbering contained in the amended Figure 3a.

Likewise, the indicator lines leading from the labels 320 and 330 were transposed in the drawings as provided in the January 1, 2003 response, and are amended to point to the correct features. Thus, the indicator line from label 320 is corrected to point to the underfill, and the indicator line from label 330 is corrected to point to the die. These changes also bring the amended Figure 3a into agreement not only with the specification as amended in applicants' January 1, 2003 response ("with underfill 320 shown protruding from underneath and just beyond the edges of die 330"), but also with the

similar die and underfill features shown in Figure 4a, (320 in Figure 3a corresponding to 420 in Figure 4a, etc.).

The application serial number has been added as identifying indicia on the front of the sheet for Figure 3a in accordance with 37 CFR 1.84(c).


CONCLUSION

Therefore, applicants' respectfully request approval of the amendments to Figure 3a as submitted herein, as they correct simple transposition and typographical errors in the figure as previously submitted, and place the application in proper condition for issuance.

Please charge any shortages and credit any overages to Deposit Account No. 02-2666.


Respectfully submitted,

Date: June 17, 2005



Patrick D. Boyd
Registration No. 54,671

12400 Wilshire Blvd.
Seventh Floor
Los Angeles, CA 90025
(503) 439-8778



Marked Amended Sheet
Appl. No. 09/751,214




Fig. 3a